

WOKIN CIRCULAR SAW 1300W|787313

PARTS LIST

Part	Description	Qty	Part	Description	Qty
1	Sticker	1	37	Screw ST4.2×60	2
2	Upper cover	1	38	Stator	1
3	Hex wrench M8×16	1	39	Connect pin 8.5	2
4	Big washer 8X22X2	1	40	Bearing 607-2RS	1
5	Outer flange	1	41	Bearing jacket	1
6	Blade	1	42	Housing	1
7	Clamplng flange	1	43	Specification sticker	1
8	screw M4×10	6	44	Carton brush cover	2
9	Flange for lower guard	1	45	Carbon brush	2
10	Lower guard	1	46	Brush holder 6×10×24	2
11	Screw M4×8	1	47	Rear cover	1
12	Spanner for lower guard	1	48	Screw ST4.2×16-F	8
13	Spring $\phi 3.8 \times 0.7 \times 98$	1	49	Screw M5×50	2
14	Output shaft	1	50	Left handle	1
15	Semi-circular key 3×10	1	51	capacitor 0.22 μ F×2	1
16	bearing 6001-2RS	1	52	Switch	1
17	Front cover	1	53	Right handle	1
18	Washer 12	1	54	Cable presser 70T-16-02	1
19	Big gear	1	55	Cable jacket 10T-20	1
20	Washer 10	1	56	Cable 2×0.75mm ²	1
21	Screw M6×18	1	57	riviter 5×7	2
22	Bearing 8C7×14×8	1	58	Locking knob	1
23	Screw M5×18	1	59	Flat washer $\phi 6 \times \phi 14 \times 1.5$	2
24	Washer	1	60	Angle frame	1
25	Elastic cylindrical pin 6×35	1	61	nut M4	1
26	Head cover	1	62	Screw M4×10	1
27	Screw M4×12	4	63	Spring $\phi 8.2 \times 0.8 \times 3$	1
28	washer 4	3	64	Pressing knob	1
29	Screw M5×35	1	65	Bolt M6×14	1
30	Rear cover for exit dust	1	66	Base	1
31	Board	1	67	locking rob for depth	1
32	Self-pin	1	68	Depth frame	1
33	Bearing 6000-2RS	1	69	Spanner 6	1
34	Spring $\phi 5.9 \times 0.7 \times 10$	1	70	Parallel guide	1
35	Rotor	1			
36	Wind fence	1			

ASSEMBLY DIAGRAM

