

PARTS LIST

784040

Part	Description	Qty
1	Screw M5x18	1
2	Drill Chuck	1
3	Spindle	1
4	6200 Bearing	1
5	Screw M4x16	1
6	Gear Wheel	1
7	Steel Ball	1
8	626 Bearing	2
9	607 Bearing	1
10	Rotor	1
11	Stator	1
12	Label	2

Part	Description	Qty
13	Left Housing	1
14	Carbon Brush	2
15	Brush Holder	2
16	Dial Button	1
17	Screw ST4x16	8
18	Right Housing	1
19	Switch	1
20	Screw ST4x14	2
21	Cord Clamp	1
22	Cord protector	1
23	Cord and plug	1

ASSEMBLY DIAGRAM

784040

