

PARTS LIST

No.	Part name	Qty	No.	Part name	Qty
1	Outer Flange	1	24	Ring	1
2	Grinding wheel	1	25	Gasket $\phi 7 \times \phi 14 \times 0.3$	1
3	Inner Flange	1	26	607 bearing	1
4	Wheel cover	1	27	607 bearing sleeve	1
5	output shaft	1	28	Fad Guid	1
6	Dust cover	1	29	Screw ST4 $\times 70$	2
7	Screw M4 $\times 14$	4	30	Stator	1
8	Front cover	1	31	Screw ST3 $\times 10$	4
9	6201 bearing	1	32	Carbon brush	2
10	Spring ring 32	1	33	Brush holder	2
11	Big gear	1	34	Coil spring	2
12	Needle roller bearing HK0808	1	35	Lebal	1
13	Self locking pin	1	36	Switch	1
14	Pinion	1	38	Motor housing	1
15	M6 nut	1	39	Wire plate	1
16	Screw ST4 $\times 20$	4	40	Screw ST4 $\times 14$	2
17	Self locking spring	1	41	Cord guard	1
18	Self locking cap	1	42	Wiring cap	1
19	Gear cover	1	43	Back cover	1
20	O-ring $\phi 21.5 \times \phi 1.8$	1	44	Power cord	1
21	608 bearing	1	45	Screw ST4 $\times 12$	2
22	Self locking pin	1	46	Wrench	1
23	Armature	1			

ASSEMBLY DIAGRAM