

WOKIN BELT SANDER 810W | 783008

PARTS LIST

Part	Description	Qty	Part	Description	Qty
1	Speed controller	1	32	Cable jacket	1
2	Blocking ring	1	33	Left housing	1
3	Capacitance	1	34	Brand label	1
4	Blocking ring 10	1	35	Column melt 3×16	1
5	Switch	1	36	Round pin	1
6	Stator	1	37	Washer 8	1
7	Bearing	1	38	Washer 8	1
8	Tension spring $\phi 12$	2	39	Adjustable knob	1
9	Screw ST4.2×45-F	2	40	Spring	1
10	Bearing	4	41	Carbon brush cover	1
11	Tension supporting	1	42	Carbon brush	2
12	Tension spring $\phi 11.5 \times \phi 2 \times 6$	1	43	Brush holder	2
13	Tension wheel	1	44	Ceramic chip	1
14	Rotor	1	45	Screw	1
15	Tension pole	1	46	Wahser	1
16	Bearing 6000-2Z	2	47	Cable	1
17	Reset spring $\phi 5.4 \times \phi 1.2 \times 8$	1	48	Bearing 626	1
18	Rivet 6×10	1	49	Axis	1
19	BELT	1	50	Bearing 6900-2Z	1
20	Screw ST4.2×14-F	17	51	Dust base	1
21	Right housing	1	52	Small drawing wheel	1
22	Screw ST4.2X30	3	53	Fan	1
23	Bracket base	1	54	Fan cover	1
24	Rubber washer	1	55	Belt	1
25	Baseplate	1	56	Washer 10	1
26	Wollen washer	1	57	Big wheel	1
27	Drawing whee	1	58	Belt cover	1
28	Oil bearing	1	59	SPEC label	1
29	Screw ST2.9	1	60	Dust pipe	1
30	Ceramic chip	1	61	Supportting steel-wire	1
31	Cable presser	1	62	Dust bag	1

783008 | 810W

BELT SANDER

WOKIN

ASSEMBLY DIAGRAM

