


WOKIN VACUUM CLEANER 2000W | 794207

ASSEMBLY DIAGRAM



PARTS LIST

NO.	Part name	Qty	NO.	Part name	Qty
1	Handbar screw 4x80	8	31	Cotton bag	1
2	Handbar	1	32	Clamps sets	2
3	Switch	2	33	Water out sets	1
4	Top cover screw 4x65	2	34	Screw 4x12	8
5	Top cover screw 4x25	5	35	Side hand bar	2
6	Top cover	1	36	Hose frame	2
7	Screw 4x18	2	37	M5x20	4
8	Cabel press board	1	38	Screw 4x20	7
9	Cabel	1	39	Tank 70l	1
10	Cabel protector	1	40	Air-inlet ring	1
11	Top cover screw 4x55	2	41	Air-inlet base	1
12	Line hole cover	1	42	Hose	1
13	Middle cover	1	43	Wheels	2
14	Resistance capacitor	2	44	Water outlet sets	1
15	Motor cooling seal	2	45	Metal tube sets	1
16	Top cover screw 4x45	3	46	Base	1
17	Motor cover	1	47	Static chain	1
18	Sealing ring of motor	2	48	Big wheels sets	2
19	Motor noise reduction sponge	2	49	Rear wheel clamps set	1
20	Motor	2	50	Rear wheel alex	1
21	Sealing ring of motor	2	51	Screw 4x16	11
22	Angel frame 19+20	3	52	Big nozzle	1
23	Botton cover	1	53	Floor brush for dry	1
24	Seal for botton cover	1	54	Floor brush for wet	1
25	Seal cover for botton	1	55	Round brush	1
26	Safety valve	1	56	Screw 5x20	7
27	Botton cover bascket	1	57	Screw 5x40	2
28	Push rod	1	58	Foam filter for wet	1
29	Iron alex	1	59	Wind cover	1
30	Cotton bag frame	1			